



ecology and environment, inc.

International Specialists in the Environment

1999 Bryan Street


Dallas, Texas 75201

Tel: (214) 220-0318, Fax: (214) 855-1422

MEMORANDUM

TO: Chris Petersen, DPO
EPA Region 6

THRU: Chris Quina, TATL
Region 6 Technical Assistance Team

FROM: Steven Cowan 
Region 6 Technical Assistance Team

DATE: July 29, 1994

REF: TAT Contract Number 68-WO-0037
TDD #: T06-9405-905
PAN #: E06Z170VAA

SUBJECT: Narrative Summary
Goodson & Sons Trucking Landfill, Channelview, TX
CERCLIS #: TXD981052475

INTRODUCTION

The Region 6 Technical Assistance Team (TAT) was tasked by the U. S. Environmental Protection Agency (EPA) to review the existing EPA Region 6 CERCLIS file for Goodson & Sons Trucking Landfill so a final decision can be made by EPA as to the site's current CERCLIS status. The file was reviewed for CERCLA eligibility, RCRA status, Subtitle D status or Texas Water Commission (TWC) enforcement action, in addition to relevant Hazard Ranking System (HRS) data. Based on the file review, the EPA has made a decision to give Goodson & Sons Trucking Landfill a classification of No Further Remedial Action Planned (NFRAP). This memorandum will briefly describe the information obtained from the file that lead to a site classification of NFRAP for the Goodson & Sons Trucking Landfill site.

SITE HISTORY AND DESCRIPTION

The Goodson & Sons Trucking Landfill site, which is located in Channelview, Texas, is an inactive landfill which had alleged dumping of solvents. Flue dust waste also disposed in the landfill. Sampling of soil and surface water found no organic contamination. The only contaminants that may be attributed to the site are calcium, potassium and sodium. The site screening assessment in 1990 found no evidence of solvents, leachates or odors associated with the site.

REGULATORY STATUS OF SITE

A Site Inspection was performed in 1987. The facility had no operational permits.

